

Seat Lift Mechanism:

Ensure that the red cap has been removed prior to assembly otherwise the seat height will not adjust.

