


Please do not tighten the screws when assembling the top crossbeam.



Please tighten the screws after Assembled all the beams.